

## 法務部矯正署宜蘭監獄工程或環境興革表

作 業 科

興革日期：100 年 8 月 16 日

**興革事項：**本監右教區工場屋頂防水施作。

**內容說明：**右教區屋頂防水層使用已逾十餘年未曾翻新，致部分區域防水層損壞並導致屋頂產生漏水現象，經本監營繕隊重新整修施工後業已完成該區之四個工場（九至十二工）及一個舍房（平二舍）之防水工程施工。

**對照表：**

相片 (地點)	改善前 (施工中)	改善後
九工場屋頂		
九工場屋頂施工		

<p>十工場屋頂</p>		
<p>十工場屋頂施工</p>		
<p>十工場屋頂施工</p>		
<p>十一工場屋頂</p>		

<p>十一工場屋頂施工</p>	 A wide-angle shot of a flat roof under construction. Two workers in white shirts and blue shorts are visible. One is pushing a blue wheelbarrow across the dark, wet surface. The background shows palm trees and a clear sky.	 Two workers are applying a material to a roof. One worker is wearing a traditional conical hat. They are using long-handled tools to spread the material. A large palm tree is in the foreground, and a building is visible in the background.
<p>十一工場屋頂施工</p>	 A large area of water on a roof, reflecting the blue sky and clouds. The water is contained within a low wall. In the background, there are palm trees and mountains.	 Three workers are on a wet roof, likely applying a waterproofing layer. They are using long-handled rollers. The background features a building and mountains under a cloudy sky.
<p>十二工場屋頂</p>	 A view of a roof with water on it. In the background, a tall, white, cylindrical water tower stands against a backdrop of green mountains. The sky is overcast.	 A view of a finished roof surface, which is now a uniform, bright white color. The water tower and mountains are visible in the background under a clear blue sky.
<p>十二工場屋頂施工</p>	 Two workers are on a wet roof, applying a material. A water tower is visible in the background. The workers are wearing white shirts and blue shorts.	 A view of a roof with water on it, reflecting the sky. A water tower is visible in the background. The sky is cloudy.

<p>十二工場屋頂施工</p>		
<p>和二舍屋頂</p>		
<p>和二舍屋頂</p>		
<p>其它相關相片</p>		
		

